

2007 Tundra Headlamp Connector Service Part 82824-60460

- The headlamp low beam connector is now available as a service part through Toyota dealers.
- The same part number applies to right hand (RH) and left hand (LH) low beam lamps.

